

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From:
Sri C.Viswanatha Reddy, M.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

✓ To:
The Principal,
Dr. K.L.P Public School,
J.K.C College Road,
Ring Road,
Guntur.

Letter No. Soundness Certificate / EC-III / GNT / 2026, Dated : 16.03.2026

Sub :-(R&B) Division, Guntur – Structural Soundness Certificates – “Dr.K.L.P.Public School, JKC College Road, Ring Road, Guntur- Issue-Regarding.

Ref :- 1) Representation received by Dr K.L.P Public School, Guntur Dated:-11.03.2025.

With reference to the above, I have personally inspected the " Dr Kondabolu Lakshmi Prasad Public School (Senior Secondary)", on 13.03.2026 which was located in JKC College Road, Ring Road,, Guntur The existing building RCC framed structures (G+3) Constructed in the year 1983 is utilizing for class.

It is observed that the doors, windows and toilets are in good condition on visual observation, it is observed that the above building is **Structurally sound** as on 13.03.2026 to 12.03.2027 one year.

Encl:- Soundness Certificate.

Yours faithfully,


16/03/26
Executive Engineer
(R&B) Division, Guntur

16/3/26

SOUNDNESS CERTIFICATE

This is to certify that I have personally inspected the " Dr Kondabolu Lakshmi Prasad Public School (Senior Secondary)" on 13.03.2026 which was located in JKC College Road, Ring Road,, Guntur The existing building RCC framed structures (G+3) Constructed in the year 1983 is utilizing for class.

It is observed that the doors, windows and toilets are in good condition On visual observation, it is observed that the above building is **Structurally sound** as on 13.03.2026 to 12.03.2027 one year.


16/03/26
Executive Engineer
(R&B) Division, Guntur


16/3/26